













4 30 05 224 3 30 39 050 4 30 53 068 ČSN 02 11 53 1.1.1.1 1.1.1.1 4 30 30 190 4 12 41 042 4 30 51 042

4 30 41 282

4 30 11 529

ČSN 02 14 03 1.1.1.1 1.1.1.1

ČSN 02 21 05 08 1.1.1.1 1.1.1.1

ČSN 02 21 95 07 1.1.1.1 1.1.1.1

ČSN 02 25 62 1.1.1.1 1.1.1.1

3 12 11 26 94

4 30 24 075

4 30 30 513

4 30 51 048

4 30 18 027

ČSN 02 11 51 1.1.1.1 1.1.1.1

4 30 05 066


PLAČÍTKO 1.1.1.1 1.1.1.1

ÚN 02 94 01 1.1.1.1 1.1.1.1

4 30 30 091

ČSN 02 11 53 1.1.1.1 1.1.1.1

2 30 31 005 4 30 30 048 4 30 41 040 3 30 57 051 ČSN 02 25 62 1.1.1.1 1.1.1.1 3 30 11 194 ČSN 02 14 03 1.1.1.1 1.1.1.1 4 30 51 040 ČSN 02 36 80 1.1.1.1 1.1.1.1 3 30 03 054 4 30 15 007 ČSN 02 11 53 1.1.1.1 1.1.1.1 4 30 52 129 4 30 52 128 1.1.1.1 1.1.1.1



3 12 16 26 15 4 12 17 26 92 ČSN 02 36 80 1.1.1.1 1.1.1.1 4 12 16 18 02 4 12 16 26 91 ČSN 02 25 62 1.1.1.1 1.1.1.1 4 12 24 26 93

4 30 31 13

4 30 17 12 79

4 30 53 069

4 30 18 074

ČSN 02 25 62 1.1.1.1 1.1.1.1

ČSN 02 11 53 1.1.1.1 1.1.1.1


ČSN 02 29 30 1.1.1.1 1.1.1.1



3 12 11 26 94

4 30 30 086


4 12 24 038


4 30 23 055






24 50







4 30 05 224 3 30 39 050 4 30 58 068 ČSN 02 11 33 4 30 30 190 4 12 41 042 4 30 51 192 3 12 16 26 15 4 12 17 26 92 ČSN 02 38 93 4 12 16 12 82 4 12 16 26 91 ČSN 02 25 62 4 12 24 26 93

4 30 41 292

4 30 11 599

ČSN 02 14 03
H 11 14

ČSN 02 21 95 08
H 11 14

ČSN 02 21 95 02
H 21 18

ČSN 02 25 62
H 11 14 14

3 12 11 26 94

4 30 24 075

4 30 30 313

16 26 15

4 30 51 043

4 30 18 027

ČSN 02 11 51
H 4 1 30 34


4 30 05 066

PLAČITKO
TAK 1/2

UN 02 94 01
SUPERO 20 40 1/2

4 30 30 091

ČSN 02 11 33
H 5 14 34



4 30 30 313

4 30 17 10 99

4 30 53 069

4 30 18 074

ČSN 02 25 62
H 11 14

ČSN 02 11 53
H 11 14 34

ČSN 02 29 30
H 11 14 34


3 12 11 26 94


4 30 30 086


4 12 24 038


4 30 23 055


2 30 31 005 4 30 30 043 4 30 41 040 3 30 57 051 ČSN 02 25 62 3 30 11 194 ČSN 02 11 33 4 30 51 040 ČSN 02 38 93 3 30 03 054 4 30 15 007 ČSN 02 11 33 4 30 52 129 4 30 52 123





















SU 50 A



PRO NADĚTI STROJE 3x500-550V KONTROLKA K3 ZAPOJENA NA SVORKY 14-15



POLOHA	I	0	II
KONTAKT			
1a	55 - 56		*
1b	55 - 52	*	
2	52 - 53	*	

